

# Product Update Notification

## Unismart 3 DBBASE V2.09

Date: Jan, 2021

### 1. Unismart 3 Device

Item	Before	After
APP	<V23.0	V24.0
DBBASE	<V2.07	V2.09
H20-2	V0.6	V1.2

### 2. Uni-3 New JIG (N/A)

H20-2 (Use the JIG H20, and manually update to H20-2 program)

### 3. Update Instructions:

- ① The upgraded program is compatible to old version chips with PCB code 7H1110 & 7H2210.
- ② For special and universal CF500 models, please do the operations under H20-2 V1.2 program.

### 4. Uni-3 New Added Blank Chip List(N/A)

### 5. Uni-3 New Added Model List(N/A)

### 6. Uni-3 Update Model List

Brand	PCB Code	OEM Code	JIG	Version	Color	Yield	Region	For Use in Printers
HP	PCB-B73	CF500A-N/CRG-054K-V2	H20-2	V1.2	K	1.4K	WW	HP LaserJet Pro M254dw/ 254nw/M280nw/M281fdw/ 281fdn Canon i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Color Image Class MF642Cdw/
HP	PCB-B73	CF501A-N/CRG-054C-V2	H20-2	V1.2	C	1.3K	WW	
HP	PCB-B73	CF502A-N/CRG-054Y-V2	H20-2	V1.2	Y	1.3K	WW	
HP	PCB-B73	CF503A-N/CRG-054M-V2	H20-2	V1.2	M	1.3K	WW	
HP	PCB-B73	CF500X-N/CRG-054HK-V2	H20-2	V1.2	K	3.2K	WW	
HP	PCB-B73	CF501X-N/CRG-054HC-V2	H20-2	V1.2	C	2.5K	WW	
HP	PCB-B73	CF502X-N/CRG-054HY-V2	H20-2	V1.2	Y	2.5K	WW	



HP	PCB-B73	CF503X-N/CRG-054HM-V2	H20-2	V1.2	M	2.5K	WW	MF641Cw/MF644Cdw/ LBP622Cdw
HP	PCB-B73	CF540A-N/CRG-054K-V2	H20-2	V1.2	K	1.4K	WW	HP Color LaserJet Pro M254dw/254nw, MFP M280nw, MFP M281fdw/ 281fdn
HP	PCB-B73	CF541A-N/CRG-054C-V2	H20-2	V1.2	C	1.3K	WW	
HP	PCB-B73	CF542A-N/CRG-054Y-V2	H20-2	V1.2	Y	1.3K	WW	Canon i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Color Image ClassMF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw
HP	PCB-B73	CF543A-N/CRG-054M-V2	H20-2	V1.2	M	1.3K	WW	
HP	PCB-B73	CF540X-N/CRG-054HK-V2	H20-2	V1.2	K	3.2K	WW	HP LaserJet Pro M254dw/ 254nw/M280nw/M281fdw/ 281fdn/M252dn/252n, MFP M277dw/277n, MFP M274n
HP	PCB-B73	CF541X-N/CRG-054HC-V2	H20-2	V1.2	C	2.5K	WW	
HP	PCB-B73	CF542X-N/CRG-054HY-V2	H20-2	V1.2	Y	2.5K	WW	Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara LBP612C/ LBP611C/MF634Cdw/ MF632Cdw
HP	PCB-B73	CF543X-N/CRG-054HM-V2	H20-2	V1.2	M	2.5K	WW	
HP	PCB-B73	CF500/400A-N/CRG-045K/054K-V2	H20-2	V1.2	K	1.4K	WW	HP Color LaserJet Pro M254dw/254nw, MFP M280nw, MFP M281fdw/ 281fdn/M252dn/252n, MFP M277dw/277n, MFP M274n, Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF501/401A-N/CRG-045C/054C-V2	H20-2	V1.2	C	1.3K	WW	
HP	PCB-B73	CF502/402A-N/CRG-045Y/054Y-V2	H20-2	V1.2	Y	1.3K	WW	Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF503/403A-N/CRG-045M/054M-V2	H20-2	V1.2	M	1.3K	WW	
HP	PCB-B73	CF500/400X-N/CRG-045HK/054HK-V2	H20-2	V1.2	K	3.2K	WW	HP LaserJet Pro M254dw/ 254nw/M280nw/M281fdw/ 281fdn/M252dn/252n, MFP M277dw/277n, MFP M274n, Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF501/401X-N/CRG-045HC/054HC-V2	H20-2	V1.2	C	2.5K	WW	
HP	PCB-B73	CF502/402X-N/CRG-045HY/054HY-V2	H20-2	V1.2	Y	2.5K	WW	Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF503/403X-N/CRG-045HM/054HM-V2	H20-2	V1.2	M	2.5K	WW	
HP	PCB-B73	CF540/400A-N/CRG-045K/054K-V2	H20-2	V1.2	K	1.4K	WW	HP Color LaserJet Pro M254dw/254nw, MFP M280nw, MFP M281fdw/ 281fdn/M252dn/252n, MFP M277dw/277n, MFP M274n, Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF541/401A-N/CRG-045C/054C-V2	H20-2	V1.2	C	1.3K	WW	
HP	PCB-B73	CF542/402A-N/CRG-045Y/054Y-V2	H20-2	V1.2	Y	1.3K	WW	Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF543/403A-N/CRG-045M/054M-V2	H20-2	V1.2	M	1.3K	WW	
HP	PCB-B73	CF540/400X-N/CRG-045HK/054HK-V2	H20-2	V1.2	K	3.2K	WW	HP LaserJet Pro M254dw/ 254nw/M280nw/M281fdw/ 281fdn/M252dn/252n, MFP M277dw/277n, MFP M274n, Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF541/401X-N/CRG-045HC/054HC-V2	H20-2	V1.2	C	2.5K	WW	
HP	PCB-B73	CF542/402X-N/CRG-045HY/054HY-V2	H20-2	V1.2	Y	2.5K	WW	Canon Color Image Class MF634Cdw/MF632Cdw/ LBP612Cdw/MF642Cdw/ MF641Cw/MF644Cdw/ LBP622Cdw, i-SENSYS MF631Cn/633Cdw/635Cx, i-SENSYS LBP611Cn/ 613Cdw, i-SENSYS LBP621Cw/LBP623Cw/ MF641Cw/MF643Cdw/ MF645Cx, Satara
HP	PCB-B73	CF543/403X-N/CRG-045HM/054HM-V2	H20-2	V1.2	M	2.5K	WW	



HP	PCB-B73	CF543/403X-N/CRG-045HM/054HM-V2	H20-2	V1.2	M	2.5K	WW	LBP612C/LBP611C/ MF634Cdw/MF632Cdw
----	---------	---------------------------------	-------	------	---	------	----	---------------------------------------

### 7. Operations to Confirm the Updated Version

As customer has upgraded the device, please enter the Settings-Version interface to confirm the updated version by following below steps (refer to the appendix in Unismart 3 Device)




Figure 1




Figure 2




Figure 3 Versions without JIG connecting




Figure 4 Versions with JIG H20 connecting

Version list for the device & JIG (click DBBASE to check)



CHECK UPDATE	
APP	24.0
<b>DBBASE</b>	<b>2.09</b>
Price List	x.xxx
Boot	1.4

Figure 5

BROTHER	0.05
.....	
HP	0.3
.....	
SN-HP-252	0.04
SN-HP-5x0	0.01

Figure 6

SN-XEROX-7100	0.04
TALLY	0.03
TOSHIBA	0.03
UTAX	0.03
<b>VersionInfo</b>	<b>2.09</b>
XEROX	0.09

Figure 7

Hardware #1	11.4
Hardware #2	1.2
Hardware #3	0.3
.....	
H20	1.8
<b>H20-2</b>	<b>1.2</b>

Figure 8

Notice:

- 1、 Due to the H20 hardware limitation, the new and old version programs can't be saved in storage both, please update the JIG to the corresponding program manually for dedicated model's operation.
- 2、 JIG program can be switched in above steps. When the JIG is connected, please long press the desired JIG as shown in Picture 8, and click OK in prompt window. When it indicates completion in the progress bar, please check the JIG and version in the Version interface.
- 3、 Please press SCAN button in the device to confirm the chip model before resetting.
- 4、 If it reports "Wrong JIG" during the operation, please check the JIG and its version by following above steps.

"Apex" herein refers to Apex Microelectronics Co., Ltd. The information contained herein is subject to change without prior notification. Apex shall not be liable for technical or editorial errors or omissions contained herein. Photographed products may not always match the description.