



# Product Update Notification

## Unismart 3 DBBASE V2.12

Date: Mar 2021

### 1. Unismart 3 Device

Item	Before	After
APP	<V23.0	V24.0
DBBASE	<V2.09	V2.12
H19	V2.8	V2.9
SAMSUNG	V0.17	V0.20

### 2. Uni-3 New JIG (N/A)

### 3. Update Instructions:

Have updated the scan algorithm of Samsung MLT-D115 V4 series products, improving the scan speed.

### 4. Uni-3 New Added Blank Chip List(N/A)

### 5. Uni-3 New Added Model List(N/A)

### 6. Uni-3 Update Model List

Brand	PCB Code	OEM Cartridge	JIG	Color	Yield	Region	For Use in Printers
SAMSUNG	PCB-B62	MLT-D111S-DOM-V4	H19	1K	BK	DOM	Samsung SL-M2020/2020W/ M2022/2022W/2070/2070W /2070F/2070/M2071/2074FW/ SL-M2026/M2077/M2078/ 2078F/2078FW
SAMSUNG	PCB-B62	MLT-D111S-DOM-DZ-V4	H19	1K	BK	DOM	
SAMSUNG	PCB-B62	MLT-D111S-EUR-V4	H19	1K	BK	EUR	
SAMSUNG	PCB-B62	MLT-D111S-EXP-V4	H19	1K	BK	EXP	
SAMSUNG	PCB-B62	MLT-D111S-MEA-V4	H19	1K	BK	MEA	
SAMSUNG	PCB-B62	MLT-D111L-DOM-V4	H19	1.8K	BK	DOM	
SAMSUNG	PCB-B62	MLT-D111L-DOM-DZ-V4	H19	1.8K	BK	DOM	
SAMSUNG	PCB-B62	MLT-D111L-EUR-V4	H19	1.8K	BK	EUR	
SAMSUNG	PCB-B62	MLT-D111L-EXP-V4	H19	1.8K	BK	EXP	
SAMSUNG	PCB-B62	MLT-D111L-MEA-V4	H19	1.8K	BK	MEA	
SAMSUNG	PCB-B62	MLT-D115L-CHN-V4	H19	3K	BK	CHN	
SAMSUNG	PCB-B62	MLT-D115L-DOM-V4	H19	3K	BK	DOM	



SAMSUNG	PCB-B62	MLT-D115L-DOM-DZ-V4	H19	3K	BK	DOM	M2670N/2670FN/2870FW/ 2870FD/2880FW/M2621/ M2671N/2671FH
SAMSUNG	PCB-B62	MLT-D115L-EUR-V4	H19	3K	BK	EUR	
SAMSUNG	PCB-B62	MLT-D115L-EXP-V4	H19	3K	BK	EXP	
SAMSUNG	PCB-B62	MLT-D115L-MEA-V4	H19	3K	BK	MEA	
SAMSUNG	PCB-B62	MLT-D112S-CHN-V4	H19	1K	BK	CHN	Samsung SL-M2023/M2029
SAMSUNG	PCB-B62	MLT-D110L-CHN-V4	H19	1.5K	BK	CHN	Samsung SL-M2060/W/FW/NW
SAMSUNG	PCB-B68	MLT-D204S-CHN-V4	H19	3K	BK	CHN	Samsung SL-M3325/3825/ 4025/M3375/3875/4075
SAMSUNG	PCB-B68	MLT-D204S-DOM-V4	H19	3K	BK	DOM	
SAMSUNG	PCB-B68	MLT-D204S-DOM-DZ-V4	H19	3K	BK	DOM	
SAMSUNG	PCB-B68	MLT-D204S-EUR-V4	H19	3K	BK	EUR	
SAMSUNG	PCB-B68	MLT-D204S-EXP-V4	H19	3K	BK	EXP	
SAMSUNG	PCB-B68	MLT-D204S-MEA-V4	H19	3K	BK	MEA	
SAMSUNG	PCB-B68	MLT-D204L-CHN-V4	H19	5K	BK	CHN	
SAMSUNG	PCB-B68	MLT-D204L-DOM-V4	H19	5K	BK	DOM	
SAMSUNG	PCB-B68	MLT-D204L-DOM-DZ-V4	H19	5K	BK	DOM	
SAMSUNG	PCB-B68	MLT-D204L-EUR-V4	H19	5K	BK	EUR	
SAMSUNG	PCB-B68	MLT-D204L-EXP-V4	H19	5K	BK	EXP	
SAMSUNG	PCB-B68	MLT-D204L-MEA-V4	H19	5K	BK	MEA	
SAMSUNG	PCB-B68	MLT-D204U-CHN-V4	H19	15K	BK	CHN	
SAMSUNG	PCB-B68	MLT-D204U-DOM-V4	H19	15K	BK	DOM	
SAMSUNG	PCB-B68	MLT-D204U-DOM-DZ-V4	H19	15K	BK	DOM	
SAMSUNG	PCB-B68	MLT-D204U-EUR-V4	H19	15K	BK	EUR	
SAMSUNG	PCB-B68	MLT-D204U-EXP-V4	H19	15K	BK	EXP	
SAMSUNG	PCB-B68	MLT-D204U-MEA-V4	H19	15K	BK	MEA	
SAMSUNG	PCB-B69	CLT-R708-V4	H19	200K	Drum	---	Samsung MultiXpress K4300LX/K4350LX/K4250LX
SAMSUNG	PCB-B69	MLT-D708S-DOM-DZ-V4	H19	25K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D708S-DOM-V4	H19	25K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D708S-EUR-V4	H19	25K	BK	EUR	
SAMSUNG	PCB-B69	MLT-D708S-EXP-V4	H19	25K	BK	EXP	
SAMSUNG	PCB-B69	MLT-D708S-MEA-V4	H19	25K	BK	MEA	
SAMSUNG	PCB-B69	MLT-D708L-DOM-DZ-V4	H19	35K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D708L-DOM-V4	H19	35K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D708L-EUR-V4	H19	35K	BK	EUR	
SAMSUNG	PCB-B69	MLT-D708L-EXP-V4	H19	35K	BK	EXP	
SAMSUNG	PCB-B69	MLT-D708L-MEA-V4	H19	35K	BK	MEA	
SAMSUNG	PCB-B69	CLT-C808S-DOM-DZ-V4	H19	20K	C	DOM	



SAMSUNG	PCB-B69	CLT-C808S-DOM-V4	H19	20K	C	DOM	X4300LX/X4250LX/X4220RX
SAMSUNG	PCB-B69	CLT-K808S-DOM-DZ-V4	H19	23K	BK	DOM	
SAMSUNG	PCB-B69	CLT-K808S-DOM-V4	H19	23K	BK	DOM	
SAMSUNG	PCB-B69	CLT-M808S-DOM-DZ-V4	H19	20K	M	DOM	
SAMSUNG	PCB-B69	CLT-M808S-DOM-V4	H19	20K	M	DOM	
SAMSUNG	PCB-B69	CLT-Y808S-DOM-DZ-V4	H19	20K	Y	DOM	
SAMSUNG	PCB-B69	CLT-Y808S-DOM-V4	H19	20K	Y	DOM	
SAMSUNG	PCB-B69	CLT-C808S-EUR-V4	H19	20K	C	EUR	
SAMSUNG	PCB-B69	CLT-K808S-EUR-V4	H19	23K	BK	EUR	
SAMSUNG	PCB-B69	CLT-M808S-EUR-V4	H19	20K	M	EUR	
SAMSUNG	PCB-B69	CLT-Y808S-EUR-V4	H19	20K	Y	EUR	
SAMSUNG	PCB-B69	CLT-C808S-EXP-V4	H19	20K	C	EXP	
SAMSUNG	PCB-B69	CLT-K808S-EXP-V4	H19	23K	BK	EXP	
SAMSUNG	PCB-B69	CLT-M808S-EXP-V4	H19	20K	M	EXP	
SAMSUNG	PCB-B69	CLT-Y808S-EXP-V4	H19	20K	Y	EXP	
SAMSUNG	PCB-B69	CLT-C808S-MEA-V4	H19	20K	C	MEA	
SAMSUNG	PCB-B69	CLT-K808S-MEA-V4	H19	23K	BK	MEA	
SAMSUNG	PCB-B69	CLT-M808S-MEA-V4	H19	20K	M	MEA	
SAMSUNG	PCB-B69	CLT-Y808S-MEA-V4	H19	20K	Y	MEA	
SAMSUNG	PCB-B69	MLT-D758S-DOM-DZ-V4	H19	25K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D758L-DOM-DZ-V4	H19	41K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D303E-DOM-DZ-V4	H19	40K	BK	DOM	Samsung SL-M4580FX
SAMSUNG	PCB-B69	MLT-D303E-EUR-V4	H19	40K	BK	EUR	
SAMSUNG	PCB-B69	MLT-D303E-EXP-V4	H19	40K	BK	EXP	
SAMSUNG	PCB-B69	MLT-D303E-MEA-V4	H19	40K	BK	MEA	
SAMSUNG	PCB-B69	MLT-D304L-DOM-V4	H19	20K	BK	DOM	Samsung SL-M4583FX/ M4530NX
SAMSUNG	PCB-B69	MLT-D304L-MEA-V4	H19	20K	BK	MEA	
SAMSUNG	PCB-B69	MLT-D304L-EXP-V4	H19	20K	BK	EXP	
SAMSUNG	PCB-B69	MLT-D304L-EUR-V4	H19	20K	BK	EUR	
SAMSUNG	PCB-B69	MLT-D304E-DOM-V4	H19	40K	BK	DOM	
SAMSUNG	PCB-B69	MLT-D304E-EUR-V4	H19	40K	BK	EUR	
SAMSUNG	PCB-B69	MLT-D304E-EXP-V4	H19	40K	BK	EXP	
SAMSUNG	PCB-B69	MLT-D304E-MEA-V4	H19	40K	BK	MEA	
SAMSUNG	PCB-B69	MLT-K858S-DOM-DZ-V4	H19	23K	BK	DOM	Samsung SL-X4255LX/ SL-X4225RX/SL-X4305LX
SAMSUNG	PCB-B69	MLT-C858S-DOM-DZ-V4	H19	22K	C	DOM	
SAMSUNG	PCB-B69	MLT-M858S-DOM-DZ-V4	H19	22K	M	DOM	



SAMSUNG	PCB-B69	MLT-Y858S-DOM-DZ-V4	H19	22K	Y	DOM	Samsung SL-M3320/3820/4020/M3370/3870/4070
SAMSUNG	PCB-B69	CLT-R858-DOM-V4	H19	100K	Drum	---	
SAMSUNG	PCB-B72	MLT-D203L-DOM-V4	H19	5K	BK	DOM	
SAMSUNG	PCB-B72	MLT-D203L-DOM-DZ-V4	H19	5K	BK	DOM	
SAMSUNG	PCB-B72	MLT-D203L-EUR-V4	H19	5K	BK	EUR	
SAMSUNG	PCB-B72	MLT-D203L-EXP-V4	H19	5K	BK	EXP	
SAMSUNG	PCB-B72	MLT-D203L-MEA-V4	H19	5K	BK	MEA	
XEROX	PCB-B68	106R02778-V4	H19	3K	BK	MEA	Xerox Work Center 3215/3225/Phaser 3052/3260
XEROX	PCB-B68	106R02775-V4	H19	1.5K	BK	EXP	Xerox Work Center 3215/3225/Phaser 3260
XEROX	PCB-B68	106R02777-V4	H19	3K	BK	EXP	

### 7. Operations to Confirm the Updated Version

As customer has upgraded the device, please enter the Settings-Version interface to confirm the updated version by following steps as below. (refer to the appendix in Unismart 3 Device)




Figure 1




Figure 2




Figure 3 Versions without JIG connecting




Figure 4 Versions with JIG connecting



Version list for the device & JIG (click DBBASE to check)

CHECK UPDATE	
APP	24.0
<b>DBBASE</b>	<b>2.12</b>
Price List	x.xxx
Boot	1.4

Figure 5

BROTHER	0.05
.....	
<b>SAMSUNG</b>	<b>0.20</b>
.....	
SN-HP-252	0.04
SN-HP-5x0	0.01

Figure 6

SN-XEROX-7100	0.04
TALLY	0.03
TOSHIBA	0.03
UTAX	0.03
<b>VersionInfo</b>	<b>2.12</b>
XEROX	0.09

Figure 7

Hardware #1	11.4
Hardware #2	1.2
Hardware #3	0.3
.....	
<b>H19</b>	<b>2.9</b>
H20	1.8

Figure 8

“Apex” herein refers to Apex Microelectronics Co., Ltd. The information contained herein is subject to change without prior notification. Apex shall not be liable for technical or editorial errors or omissions contained herein. Photographed products may not always match the description.