

Unismar 产品升级说明

日期: 2017 年 10 月

1. Unismart 设备

项目	变更前	变更后
Firmware 版本	≤V3.25.5	V3.25.6




- 进行了系统优化;

2. Uni 读写头升级

读写头编码	变更项目	变更前	变更后	变更原因
ST1	软件版本	≤V2.9	V3.1	读写头优化

Samsung MLT-D101/111 系列 PCB 板对应的型号明细如下:

U 字符	芯片图片	板号	适用型号
S1		CC4S2240	Samsung 101/504/506/117
S2		CC4S3230	Samsung 406
S3		CC4S2530	Samsung 111 /115 Xerox 2773
OS3		CC4S2540	Samsung 203
OS4		CC4S3540	Samsung 204/116 Xerox 2775/2777/2778
S5		CC4S2640	Samsung 709/809/659/358
S6		CC4S3240	Samsung 405

S7		CC4S2230	Samsung 505
S9		CC4S2770	Samsung 303/707
B03		CC4S2780	Samsung 708/808

注：前期收到客户反馈，因复位超出适用范围的型号，而导致上机不认的情况。再次申明，请用户严格按照上述型号明细表，对相应的 PCB 板芯片及型号进行复位，例如：PCB 板 S1 (CC4S2240) 只能复位适用于 101/504/506/117 型号。

如有疑问，请进一步咨询您的业务经理。