

Unismart Product Update Notification

Date: July, 2017

1. Unismart Device

Subject	Before	After
Firmware Version	≤V3.25.4	V3.25.5

- ① OEM chip reset function for Epson VII series is optimized. New models are added, the interface display is optimized.
- ② The bug that device enters an infinite loop when model loading error appeared is optimized.
- ③ The pre-reset detection function for Epson OEM chip resetting is added. Resetting the cartridge again will prompt "Chip already OK".

2. Uni-JIG Update

JIG Code	Changed Item	Before	After	Reason
EP1/H01	Software Version	≤V1.9	V2.0	Newly-added model

3. Newly-added Models

OEM product reset function for Epson VII series is added. (Please check the "Appendix I" for details)



Standard Cartridge




Starter Cartridge



Starter Cartridge



Standard Cartridge






Chip Photo

*For specific operation instructions, please visit and download the "Epson VII OEM Chip Reset Operation Instruction" in Notification of Unismart of www.apexmic.com.

If you have any questions, please consult your sales representatives.

Appendix I Uni-Newly Added Models List V3.25.5 20170719

PCB Code	Jig	Brand	Apex Product Code	OEM Product Code	For Use with
RST-EPSON-7 	 	Epson	KUI-BK/KUI-C/KUI-M/KUI-Y/KUI-LC/KUI-LM	KUIBK/KUIC/KUIM/KUIY/KUILC/KUILM	Epson EP-879AW/AB/AR (JPN)
			KUI-BK-L/KUI-C-L/KUI-M-L/KUI-Y-L/KUI-LC-L/KUI-LM-L	KUIBKL/KUICL/KUIML/KUIYL/KUILCL/KUILLML	
			34 BK/34 C/34 M/34 Y	34BK/34C/34M/34Y	Epson WorkForce Pro WF-3725DWF/3720DWF (EUR)
			34XL BK/34XL C/34XL M/34XL Y	34XLBK/34XLC/34XLM/34XLY	
			35 BK/35 C/35 M/35 Y	35BK/35C/35M/35Y	Epson WorkForce Pro WF-4740DTWF/4730DTW/4720DW/4725DW (EUR)
			35XL BK/35XL C/35XL M/35XL Y	35XLBK/35XLC/35XLM/35XLY	
			ICBK83 BK/ICC83 C/ICM83 M/ICY83 Y	ICBK83 BK/ICC83 C/ICM83 M/ICY83/Y	Epson PX-M780F/PX-M781F(JPN)
ICBK84 BK/ICC84 C/ICM84 M/ICY84 Y	ICBK84 BK/ICC84 C/ICM84 M/ICY84 Y				

"Apex" herein refers to Apex Microelectronics Co., Ltd. The information contained herein is subject to change without prior notification. Apex shall not be liable for technical or editorial errors or omissions contained herein. Photographed products may not always match the description.