



Product Update Notification

Unismart 3 DBBASE V2.01

Date: Nov, 2020

1. Unismart 3 Device

Item	Before	After
APP	<V23.0	V23.0
DBBASE	<V2.01	V2.01
Hardware #1	<V10.11	V10.11
H24	<V2.9	V2.9

2. Uni-3 New JIG (N/A)

3. Update Instructions:

- ① The device enables to update directly with WiFi connecting, and it updates the program for HP V5 series models only.
- ② This upgrade is a JIG hardware upgrade, and if the version is less than V2.8, return JIG to APEX for replacement, please.
- ③ It will not charge points for old version chips update only, however the used chips and blank chips update, and models rewriting charge points as usual.

4. Uni-3 New Added Chip List(N/A)

5. Uni-3 New Added Model List(N/A)

6. Uni-3 Update Model List

PCB Code	JIG	Brand	OEM Code	Color	Yield	Region	For Use in Printers
PCB-8Lx1x0	H24-1	SAMSUNG	MLT-K200S	K	1K	DOM	Samsung SL-M2030/M2035/2035w/2085
PCB-8Lx1x0	H24-1	SAMSUNG	MLT-K200L	K	1.5K	DOM	
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-515SK	K	1.5K	DOM	Samsung SL-C515/C565FW
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-515SC	C	1K	DOM	
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-515SM	M	1K	DOM	
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-515SY	Y	1K	DOM	
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-510SK	K	1.5K	DOM	Samsung SL-C510/C510W/C513/ C513W/C563FW/C563W



PCB-8Lx2x0	H24-2	SAMSUNG	CLT-510SC	C	1K	DOM	Samsung SL-C510/C510W/C513/ C513W/C563FW/C563W
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-510SM	M	1K	DOM	
PCB-8Lx2x0	H24-2	SAMSUNG	CLT-510SY	Y	1K	DOM	
PCB-8Lx1x0	H24-1	SAMSUNG	MLT-K250S	K	1.5K	DOM	Samsung SL-M2840ND/M2630ND/ M2893FW
PCB-8Lx1x0	H24-1	SAMSUNG	MLT-K250L	K	3K	DOM	
PCB-8Lx3x0	H24-1	XEROX	006R01731	K	13.7K	ME	Xerox B1022/B1025
PCB-8Lx4x0	H24-2	XEROX	106R04346	K	1.5K	EXP	Xerox B210/B205/B215
PCB-8Lx4x0	H24-2	XEROX	106R04347	K	3K	EXP	
PCB-8Lx4x0	H24-2	XEROX	106R04348	K	1.5K	ME	
PCB-8Lx4x0	H24-2	XEROX	106R04349	K	3K	ME	





PCB Code	JIG	Brand	OEM Code	Color	Yield	Region	For Use in Printers
PCB-8Lx1x0	H24-1	HP	W1003AC/103A	K	1.5K	CHN	HP Laser MFP 131a/133np/133pn/103a
PCB-8Lx1x0	H24-1	HP	W1004AC/104A	K	1.5K	IND	
PCB-8Lx1x0	H24-1	HP	W1105A/105A	K	1K	Mexico&LA	HP Laser MFP 135a/135w/137fnw/107a/107w
PCB-8Lx1x0	H24-1	HP	W1106A/106A	K	1K	EMEA	
PCB-8Lx1x0	H24-1	HP	W1107A/107A	K	1K	AP (ex. CHN/IND)	
PCB-8Lx1x0	H24-1	HP	W1110A/110A	K	1.5K	CHN	HP Laser MFP 136w/136a/136nw /138pn/138pnw/138p/108a/108w
PCB-8Lx1x0	H24-1	HP	W1112A/110A	K	1.5K	IND	
PCB-8Lx2x0	H24-2	HP	W2060A/116A	K	1K	AMS	HP Color Laser MFP 179fnw/ 178nw/150a/150w/150nw
PCB-8Lx2x0	H24-2	HP	W2061A/116A	C	0.7K	AMS	
PCB-8Lx2x0	H24-2	HP	W2062A/116A	Y	0.7K	AMS	
PCB-8Lx2x0	H24-2	HP	W2063A/116A	M	0.7K	AMS	
PCB-8Lx2x0	H24-2	HP	W2070A/117A	K	1K	EMEA	
PCB-8Lx2x0	H24-2	HP	W2071A/117A	C	0.7K	EMEA	
PCB-8Lx2x0	H24-2	HP	W2072A/117A	Y	0.7K	EMEA	
PCB-8Lx2x0	H24-2	HP	W2073A/117A	M	0.7K	EMEA	
PCB-8Lx2x0	H24-2	HP	W2080A/118A	K	1K	CHN	
PCB-8Lx2x0	H24-2	HP	W2081A/118A	C	0.7K	CHN	
PCB-8Lx2x0	H24-2	HP	W2082A/118A	Y	0.7K	CHN	
PCB-8Lx2x0	H24-2	HP	W2083A/118A	M	0.7K	CHN	
PCB-8Lx2x0	H24-2	HP	W2090A/119A	K	1K	APJ (ex. CHN)	
PCB-8Lx2x0	H24-2	HP	W2091A/119A	C	0.7K	APJ (ex. CHN)	
PCB-8Lx2x0	H24-2	HP	W2092A/119A	Y	0.7K	APJ (ex. CHN)	
PCB-8Lx2x0	H24-2	HP	W2093A/119A	M	0.7K	APJ(ex. CHN)	
PCB-8Lx3x0	H24-1	HP	133A/W1333A	K	7.4K	CHN	HP LaserJet MFP M435n/m437n/



PCB-8Lx3x0	H24-1	HP	133X/W1333X	K	13.7K	CHN	437dn/437nda/439n/439dn/439nda
PCB-8Lx3x0	H24-1	HP	334A/W1334A	K	7.4K	CHN	HP LaserJet MFP M42525n/42525dn/M42523n/42523d (contract machine)
PCB-8Lx3x0	H24-1	HP	334X/W1334X	K	13.7K	CHN	
PCB-8Lx3x0	H24-1	HP	335A/W1335A	K	7.4K	IND&EMEA&AP (ex. CHN)	HP LaserJet MFP 438n/M442dn/M443nda/M440dn/M440n/M440nda
PCB-8Lx3x0	H24-1	HP	335X/W1335X	K	13.7K	IND&EMEA&AP (ex. CHN)	
PCB-8Lx5x0	H24-1	HP	331A/W1331A	K	7.4K	EMEA	HP Laser 408dn/MFP 432fdn
PCB-8Lx5x0	H24-1	HP	331X/W1331X	K	13.7K	EMEA	





7. Operations to Confirm the Updated Version

As customer has updated the device, please enter the Settings-Version interface to confirm the updated version by following below steps (refer to the appendix in Unismart 3 Device)









SN-XEROX-7100	0.04
TALLY	0.03
TOSHIBA	0.03
UTAX	0.03
VersionInfo	2.01
XEROX	0.09

2020-07-27 20:34     9504 CLUS-0006



Hardware #1	10.11
Hardware #2	1.2
Hardware #3	0.3
Hardware #4	0.3
AE0	1
AE1	1

2020-07-27 20:34     9504 CLUS-0006

"Apex" herein refers to Apex Microelectronics Co., Ltd. The information contained herein is subject to change without prior notification. Apex shall not be liable for technical or editorial errors or omissions contained herein. Photographed products may not always match the description.